Record	Nο	DS	2208	
Kecolu	INU	ν	4400	

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant o	wner.) Philip Sh	ovlin Plant	t Hire L'	TD				
Address. The Brook Bennett Street West Gorton Manchester								
Address at which the examination was made.	As above							
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydraulic Excavator CASE SwL & Configuration. See load Chart						Distinguishing Number CGG0232352 Year of Manufacture. N/K Fleet No 2352		
Nature of Examination .	9(1)	9(2)	, , , , , , , , ,	9(3)(a)(i)	9(3)	(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test.	None							
Observations and condition	ons of ropes, chain	s, attachme	ents etc.					
Description			Cond	ition			WLL	Pass Y/N
Auxiliary Lifting Point			Good				5000kgs	YES
RCI (for Test Load Results	s see SP-LAFT 01))	Good				N/A	YES
within a specified time. Other defects and remedi	None							
Date of last thorough examination.						06.03.17		
Latest date by which the next thorough examination must be carried out.							08.07.19	
Date of thorough examinations of the above equation of the above equations of the above equ	quipment was thoro	oquld beco	ome a da	inger to persons	, the equiss Compl	ipment i	s safe to operate. nett Street, West G	l action
Name and Address of per	rson authenticating	report if di	ifferent	from above				
Signature Date 09.07.1					8			
Date of report 09.07.18								
						. Innui	- NI	1

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref	SP LOLER 01