Record No DS 2224

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Nature of Examination 9(1) 9(2) 9(3)(a)(i) 9(3)(a)(ii) y(3)(a)(iii) y(3)(a)(iii) y(3)(a)(iv) y(a)(a)(iv) y(a)(a)(a)(a)(a)(a)(a)(a)(a)(a)(a)(a)(a)(Employer (and or plant of	owner.) Philip Sho	ovlin Plant	Hire L	ГD				
Makers Name. SWL & Configuration. Refer to duty chart Takeuchi Refer to duty chart Refer t	Bennett Stree West Gorton Manchester Address at which the	et M12 5AU							
Particulars of any test. None Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass Y/N Auxiliary Lifting Point Good 4000kgs YES Height and Slew Limiter N/A Ill Quick Hitch TB250-3CX TEFRA S/N 78716 Good 4000kGS YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Makers Name. Takeuchi Year of Manufacture.								
Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass Y/N Auxiliary Lifting Point Good 4000kgs YES Height and Slew Limiter N/A N/A N/A Hill Quick Hitch TB250-3CX TEFRA S/N 78716 Good 4000KGS YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Nature of Examination .	9(1)	9(2)					9(3)(a)(iii)	9(3)(a)(iv)
Description Condition WLL Pass Y/N Auxiliary Lifting Point Good 4000kgs YES leight and Slew Limiter N/A N/A N/A lill Quick Hitch TB250-3CX TEFRA S/N 78716 Good 4000KGS YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 Tcertify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Particulars of any test.	None						1	
Auxiliary Lifting Point Good 4000kgs YES Height and Slew Limiter N/A N/A N/A Hill Quick Hitch TB250-3CX TEFRA S/N 78716 Good 4000KGS YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Observations and conditi	ions of ropes, chains	, attachme	nts etc.					
Height and Slew Limiter	Description			Cond	ition		_	WLL	Pass Y/N
Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Auxiliary Lifting Point			Good				4000kgs	YES
Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature				N/A				N/A	N/A
None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 28.09 Latest date by which the next thorough examination must be carried out. 17.10 Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Hill Quick Hitch TB250-3	CX TEFRA S/N 78	716	Good				4000KGS	YES
Date of last thorough examination. Latest date by which the next thorough examination must be carried out. Date of thorough examination. 17.10 Toertify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	within a specified time.	None.	or renewa	l or alte	erations required t	o reme	dy the det	fect either immed	iately or
Latest date by which the next thorough examination must be carried out. Date of thorough examination. 18.10 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature									
Date of thorough examination. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Date of last thorough examination.								28.09.1
I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	· · · · · · · · · · · · · · · · · · ·								17.10.19
to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manche Signature	Date of thorough examin	nation.							18.10.18
Qualifications. Fitter	to defects noted on this r Name and Address of C Signature	eport, which are or	could beco	me a da	inger to persons, t	he equi Compl	pment is ex, Benne	safe to operate. ett Street, West G	
Name and Address of person authenticating report if different from above	Name and Address of pe	rson authenticating	report if di	fferent	from above				
Signature Date 18.10.18	Signature				Date 18.10.18				
Date of report 18.10.18	Date of report 18.10.18								

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SPIOLER 01