

**SALES - REPAIRS - HIRE**

**SRH**

**LIFTING EQUIPMENT.**

Brook Business Complex,

Bennett St;

West Gorton,

Manchester. M12 5AU.

Mob.07852614243.

E.Mail-[eddiemalysrh@gmail.com](mailto:eddiemalysrh@gmail.com)

**LOLER REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT**

RECORD No. SRH/1020.

Name of Company. SHOVLIN PLANT HIRE LTD.

Description of equipment. CAMLOCK RAIL LIFTING CLAMPS.

Identification mark of the equipment. CL2451 – CL2452 – CL2453 – CL2456 – FR1132 – PR2104 – PR2072  
PR2075 – CR1216 – 10178-2 – PR2079.- PR2104 – SRH104 – RCS 3035 CL2455 – MR 1025 – 69144 –  
BR3951.5 – ZR2254 – BR5951.4 – DR1375 – BLS5040 – BR3697 – RR14055 – 75396 – RLS5061 – BR3951.1  
55888/15 – BR3951.3 – 77278 – 55888/16 – LBB095153 – APS02C – LBR095150 – BR3897.

Date of last thorough examination. 19-APRIL-2018.

No. of report issued on that date. SRH/0623.

The Working Load Limits and (where relevant ) corresponding radi. 1 Tonne CL2451-CL2452-CL2453-CL2456  
LBB095153,LBR095150, SRH104-CL2455-MR1025, 2 Tonne PR2104-PR2072-PR2075-PR2079 PR2104  
3.15 Tonne 10178-2.

750 kg FR1132-CR1216-RCS 3035- 69144 – BR3951.5 – ZR2254 – BR5951.4 – DR1375 – BLS5040 – BR3697  
RR14055 – 75396 – RLS5061 – BR3951.1 – 55888/15 – BR3897 – APS02C – 55888/16 – 77278 - BR3951.3

Details of any defects found (if any state NONE). NONE

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. NONE

**Declaration.**

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 27-SEPTEMBER-2018, that the above particulars are correct.

Date for completion of next thorough examination. 27-MARCH-2019.

Date. 27-SEPTEMBER-2018.

Signature of Competent Person.



Name and address of competent person and his employer, if appropriate (block letters).

E.MALY. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.

32