## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant o	<u> </u>	ovlin Plant		TD				
Address. The Brook B Bennett Stree West Gorton Manchester Address at which the examination was made.	M12 5AU							
Description of lifting equipment.  Makers Name.  SWL & Configuration.  360 Tracked Hydraulic CASE See load Chart				Ŋ			Distinguishing Number DCH13U0194 Year of Manufacture. N/K Fleet No CX194	
Nature of Examination .	9(1)	9(2)		9(3)(a)(i)	9(3)(a)(ii) X		9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test. None								
Observations and conditi	ons of ropes, chains	, attachme	nts etc.					
escription			Condition				WLL	Pass Y/N
Auxiliary Lifting Point			Good				4000kgs	YES
RCI (for Test Load Results see SP-LAFT 01)			Good				N/A	YES
State description of the d within a specified time.  Other defects and remedi	None.	or renewa	ıl or alte	erations required	to reme	edy the def	ect either immed	iately or
other defects and remedi								
None  Date of last thorough examination.							04.01.18	
Latest date by which the next thorough examination must be carried out.						22.12.19		
Date of thorough examination.								23.12.18
I certify that the above es to defects noted on this ry Name and Address of Signature	port, which are or	ould beco	me a da	inger to persons,	the equ s Comp	ipment is	safe to operate. ett Street, West G	
Qualifications. Fitter					Date	43.14.18		
Name and Address of per	rson authenticating	report if di	fferent	from above				
Signature				Date 23.12.18				
Date of report 23.12.18						., .		
-								

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01