Record No DS 2406

Fleet No

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant owner.) Philip Shovlin Plant Hire LTD

Address.

The Brook Business Complex

Bennett Street West Gorton

Manchester M12 5AU

Address at which the

examination was made. As above

Description of lifting equipment.

Makers Name.

SWL & Configuration. Refer to

360 Tracked Hydraulic Excavator Takeuchi

Refer to duty chart

Distinguishing Number 125005666

Year of Manufacture. 2017

TB250-666

Nature of Examination . 9(1) 9(2) 9(3)(a)(i) 9(3)(a)(ii) 9(3)(a)(iii) 9(3)(a)(iii) 9(3)(a)(iv)

Particulars of any test.

None

Observations and conditions of ropes, chains, attachments etc.

Description	Condition	WLL	Pass Y/N
Auxiliary Lifting Point	Good	4000kgs	YES
Height and Slew Limiter	N/A	N/A	N/A
Hill Quick Hitch TB250-3CX TEFRA S/N 78716	Good	4000KGS	YES

Identification of any part found to have a defect which is or could become a danger to persons.

None

State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time.

None.

Other defects and remedies

None

Date of last thorough examination.

06.10.23

Latest date by which the next thorough examination must be carried out.

01.10.24

Date of thorough examination.

02.10.23

I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted by this report, which are or could become a danger to persons, the equipment is safe to operate.

Name and Address of Competent Arson. Danian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester.

Signature

Date 02.10.23

Qualifications. Fi

Fitter

Name and Address of person authenticating report if different from above

Signature

Date 02.10.23

Date of report 02.10.23

Issue No:	1	
Issue Date;	Sept 2012	
No of Pages:	Page 1 of 1	
Document Ref:	SP LOLER 01	