



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/6897-10

Name of Company. SHOVLIN PLANT HIRE LTD. Brook Business Complex, Bennett St; West Gorton, M12.

Description of equipment. SAFETY HARNESS & LANYARDS.

Identification mark of the equipment. Harness 100527271 Lanyard 100515141, Harness 100680138 Lanyard 100678974, Harness 291 Lanyard 012, Harness 100431988 Lanyard 100447894, Harness 100680134 Lanyard 100678970, Harness 100680158 Lanyard 100678994, Harness 100684710 Lanyard 0167, Harness 100680157 Lanyard 0217, Harness 100680136 Lanyard 100678972, Harness 100680156 Lanyard 0133, Harness 21373766 Lanyard 21357667, Harness 21373774 Lanyard 21357661, Harness 21373770 Lanyard 21357651, Harness 21373776 Lanyard 21357649, Harness 21373775 Lanyard 21357665, Harness 1006801035 Lanyard 100678971, Harness 21373773 Lanyard 213570650, Lanyards 100678993, 100678992, 100684600, Harness 21373776 Lanyard 21357665, Harness 21373774 Lanyard 21357661, Harness 21373773 Lanyard 213576750, Harness 21373766 Lanyard 21357667, Harness CO83BA01. Harness 23034794 Lanyard 23034568, Harness 23034759 Lanyard 23034604, Harness 23034760 Lanyard 23034606,

Date of last thorough examination. 26-04-24.

No. of report issued on that date. SRH/6270-4.

The Working Load Limits and (where relevant) corresponding radi. N/A.

Details of any defects found (if any state). NONE.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. NONE.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 09-OCTOBER-2024, that the above particulars are correct.

Date for completion of next thorough examination. 09-APRIL-2025.

Signature of Competent Person. *E. Malý*

Date. 09-OCTOBER-2024.

Name and address of competent person and his employer, if appropriate (block letters).

E.MALY SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.