REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

mployer	r (and or plant o	wner.) Philip Sho	vlin Plant H	lire LTI)					
Address.	The Brook B Bennett Stree West Gorton Manchester at which the									
	ion was made.	As above								
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydrat LIEBHERR See load Chart					ılic Excavator.		Yea	Distinguishing Number K132511 Year of Manufacture. N/K Fleet No Giga L - 2511		
Nature of	Examination .	9(1)	9(2)		9(3)(a)(i)	9(3)	(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)	
Particular	rs of any test.	None								
Observati	ions and conditi	ons of ropes, chains	, attachment	ts etc.						
Descripti	on.			Condition				WLL	Pass Y/N	
Auxiliary Lifting Point				Good			7500KGS	YES		
RCI (for Test Load Results see SP-LAFT 01)				Good			N/A	YES		
DIPPER PIN				Good			10000Kgs	YES		
Geth Quick Hitch S/N 1158194				Good				10500kgs	YES	
within a s	cription of the d specified time. fects and remed	lefect and any repair None. ies None	or renewal	or alter	ations required	I to reme	dy the defe	ect either immed	ately or	
Date of last thorough examination.									20.11.23	
Latest date by which the next thorough examination must					rried out.				11.11.25	
Date of thorough examination.									12.11.24	
I certify to	that the above es s noted on this r d Address of Co	quipment was thoro eport, which are or ompetent Person. Do	could become	ne a dan	iger to persons	, the equ	ipment is s	afe to operate.		
Name an	d Address of pe	rson authenticating	report if diff	ferent fi	rom above					
Signature						Date	12.11.24			
Date of r	report 12.11.24									

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01

