Record No DS 2448

## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant owner.) Philip Shovlin Plant Hire LTD Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU Address at which the examination was made. As above Description of lifting equipment. 360 Wheeled Hydraulic Excavator Distinguishing Number K116861 Makers Name. LIEBHERR Year of Manufacture. N/K SWL & Configuration. See load Chart Fleet No Giga L - 6861 Nature of Examination. 9(1) 9(2)9(3)(a)(i)9(3)(a)(ii) 9(3)(a)(iii) 9(3)(a)(iv)  $\mathbf{X}$ Particulars of any test. None Observations and conditions of ropes, chains, attachments etc. Description Pass Y/N Condition WLL Auxiliary Lifting Point Good 7500KGS YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES DIPPER PIN Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 25/04/24 Latest date by which the next thorough examination must be carried out. 16/04/26 Date of thorough examination. 17/04/25 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Rerson, Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 17/04/25 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 17/04/25 Date of report 17/04/25

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01