Record No DS 2417

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant o	wner.) Philip Sho	ovlin Plant H	ire LTD		THE PROPERTY OF THE PROPERTY O	
Address. The Brook B Bennett Stree West Gorton Manchester		111111111111111111111111111111111111111				
Address at which the examination was made.	As above					
		ODVED TE	I DUANINI ED	Di-4ii-	Lina Nina in Dom	1 77770
Description of lifting equipment. Makers Name. SWL & Configuration. 535-95 FORKED T. JCB See Load Charts in 6			Year of Ma		ning Number RO71 ZKR anufacture. N/K N/A	
Nature of Examination .	9(1)	9(2)	9(3)(a)(i)	9(3)(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test.	None					
Observations and condition	ons of ropes, chains	, attachment	s etc.			
Description	· · · · · · · · · · · · · · · · · · ·		Condition		WLL	Pass Y/N
Auxiliary Lifting Point			N/A		N/A	YES
Height and Slew Limiter			N/A		N/A	YES
			N/A		N/A	YES
State description of the dwithin a specified time. Other defects and remedi	None.	or renewal o	or alterations require	ed to remedy the o	lefect either immedi	ately or
	None					
Date of last thorough examination.						27.04.24
Latest date by which the next thorough examination must be carried out.						24.04.26
Date of thorough examination. 25.04.						25.04.25
I certify that the above ecto defects noted on this re Name and Address of Consignature Qualifications. Fitter	eport, which are or of ompetent Person. D	ould become	e a danger to person field. Brook Busin	s, the equipment	is safe to operate. Inett Street, West Go	
Name and Address of per	rson authenticating	report if diffe	erent from above	Data 25.04.1	ne.	
Signature				Date 25.04.2	43 	
Date of report 25.04.25						

Issue No:	1	
Issue Date:	Sept 2012	
No of Pages:	Page 1 of 1	
Document Ref:	SP LOLER 01	