Record No DS 2459

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant of	owner.) Philip Sh	ovlin Plan	t Hire L	TD.		(Aloga		
Address. The Brook E Bennett Stre West Gorton Manchester	ı							
Address at which the								
examination was made.	As above							
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydrau TEREX See load Chart				ulic Excavator.		D Y F	mber. 180S301288 re. N/K 2228	
Nature of Examination.	9(1)	9(2)		9(3)(a)(i)	9(3	9(3)(a)(ii) 9(3)(a)(iii) Y		9(3)(a)(iv)
Particulars of any test. None						····		
Observations and conditi	ons of ropes, chains	s, attachme	ents etc.					
Description			Condition WLL				Pass Y/N	
Auxiliary Lifting Point			Good		12000kgs		YES	
CI (for Test Load Results see SP-LAFT 01)		Good		N/A		YES		
Quich Hitch 369961			~~~	Good		Lift Eye 10500kg		YES
Dipper Lift Point		·	Goo	od		10000k	g	YES
State description of the diwithin a specified time. Other defects and remedi	None.	or renewa	il or alte	erations required	to rem	edy the defe	ect either immedi	ately or
other defects and remedi	None							
Date of last thorough exa	mination.							15.09.24
Latest date by which the next thorough examination must be carried out.								02,09.26
Date of thorough examination.								03.09.25
I certify that the above eq to defects noted on this re Name and Address of Co Signature Qualifications. Fitter	port, which are or o	could becor	me a da	nger to persons.	the equ Comple	inment is s	afe to operate	action
	con outhouting		CC					
Name and Address of per	son aumenneating i	eport 11 a11	merent i	rom above				•
Signature					Date	03.09.25		
Date of report. 03.09.25								
						Issue No:		1

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01

